# **EXHIBIT KK**

#### SUPPLEMENT TO LAPORTE INCIDENT DESCRIPTION & FACTUAL SUMMARY

#### **Supplemental Background Information:**

On May 20, 2018, CAL FIRE publicly released its Investigation Report, 17CABTU015954, regarding the LaPorte fire. The report is publicly available via the following link on the CAL FIRE website: <a href="http://calfire.ca.gov/fire\_protection/downloads/FireReports/La%20Porte%2017">http://calfire.ca.gov/fire\_protection/downloads/FireReports/La%20Porte%2017</a> CABTU015954 Redacted.pdf.

#### **Supplemental Timeline Information:**

The LaPorte Factual Summary contained a timeline of PG&E's actions at or impacting the incident location in the period immediately preceding CAL FIRE's designated start time until service to the incident location was restored. The following additional information is relevant to the LaPorte Factual Summary timeline.

• October 8, 2017, 11:24 PM: Butte County Sheriff dispatch received a 911 report of a fire from 16 Paul Place and Darby Road, Bangor.

### **Supplemental Information Regarding Prior Inspections:**

Between September 2012 and October 2017, there were eight vegetation management inspections at or near the incident location. A number of trees were identified for work during these inspections. PG&E's understanding based upon its records is that the subject tree was not identified as needing work during any of those inspections. Between June 2012 and October 2017, there were four electric maintenance overhead patrols inspections at or near the incident location. PG&E's understanding based upon its records is that there was one electric corrective tag issued at the incident location as a result of these patrols and inspections, and it was addressed the same day. Below is a summary of vegetation management patrols and inspections and electric maintenance overhead patrols and inspections at or near the incident location.

Date	Event	Findings
8/23/2013	Western Environmental Consultants,	PG&E's understanding based on its
	Inc. ("WECI") performed a vegetation	records is that the subject tree was
	management routine patrol.	not identified for work.
11/24/2013 —	PG&E performed an electric	PG&E's understanding based upon
11/27/2013 and	maintenance overhead inspection.	its records is that one electric
12/2/2013		corrective tag was issued for the
		incident location. EC #107511521
		noted one of the subject poles was a
		missing high voltage sign. PG&E
		installed a replacement sign on the
		same day.

Date	Event	Findings
7/16/2014 —	WECI performed an aerial vegetation	PG&E's understanding based upon
8/5/2014	management Catastrophic Event	its records is that the subject tree
	Memorandum Account ("CEMA")	was not identified for work.
	patrol.	
10/10/2014	WECI performed a vegetation	PG&E's understanding based upon
	management routine patrol.	its records is that the subject tree
		was not identified for work.
6/30/2015	WECI performed an aerial vegetation	PG&E's understanding based upon
	management CEMA patrol.	its records is that the subject tree
		was not identified for work.
9/10/2015	ACRT, Inc. ("ACRT") performed a	PG&E's understanding based upon
	vegetation management routine patrol.	its records is that the subject tree
		was not identified for work.
11/19/2015	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead patrol.	its records is that no issues with
		PG&E equipment at the incident
		location were identified.
11/20/2015	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead patrol.	its records is that no issues with
		PG&E equipment at the incident
		location were identified.
4/13/2016 —	WECI performed an aerial vegetation	PG&E's understanding based upon
4/29/2016	management CEMA patrol.	its records is that the subject tree
		was not identified for work.
10/27/2016	WECI performed a vegetation	PG&E's understanding based upon
	management routine patrol.	its records is that the subject tree
		was not identified for work.
3/7/2017 —	WECI performed an aerial vegetation	PG&E's understanding based upon
3/11/2017	management CEMA patrol.	its records is that the subject tree
		was not identified for work.
10/18/2017	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead patrol.	its records is that no issues with
		PG&E equipment at the incident
		location were identified.

## **Source List:**

Source	Brief Description
CAL FIRE Report	CAL FIRE Investigation Report 17CABTU015954,
	LaPorte Fire
	http://calfire.ca.gov/fire_protection/downloads/FireR
	eports/La%20Porte%2017CABTU015954_Redacted
	<u>.pdf</u> .
Event 17-AF8208	Butte County Sheriff Public Log
PGE-CPUC_00008180- PGE-	Electric Overhead Inspection and Patrol Records
CPUC_00008193; PGE-CPUC_00008201-	
PGE-CPUC_00008211; PGE-	
CPUC_00008213-PGE-CPUC_00008217	
PGE-CPUC_00012611; PGE-CPUC_000126	Vegetation Management CEMA Records
PGE-CPUC_00011472	PG&E Annual VM Plans
PGE-CPUC_00010020-PGE-	Vegetation Management Inspection and Patrol
CPUC_00010027; PGE-CPUC_00010032-	Records
PGE-CPUC_00010036	
PGE-CPUC_00010277- PGE-	Vegetation Management Work Request Records
CPUC_00010286;	
Yubabet.com Website	https://yubanet.com/Fires/lobo/.